

Risk Assessment

Public Movements in Front of House Areas									
Venue	Buxton Opera House	exton Opera House							
Department	Front of House	Category	Front of House						
RA Reference	BUXOPFOH0031	Review	1 months						
Date of RA/review	27/06/2023	Next review	27/07/2023						
Assessor/Reviewer	Wmercer	nercer							
People at risk (estimated numbers of people	ple at risk)								
Employees	6-10	Contractors	0						
Visitors	6-10	Members of the Public	250-499						
Production staff	0	Others	0						
Client employees	0	Students	0						

Activity

General Risk Assessment for the movement of members of the public in Front of House Areas of the Opera House.

Any other relevant information

Hazard	Risk	Control measures	Risk Rating		Risk Rating		Risk Rating		Risk Rating		Risk Rating		Risk Rating		Risk Rating		Risk Rating		Risk Rating		Risk Rating		Risk Rating		Risk Rating		Risk Rating		ting	Actions	Re	vised	RR
			L	S	RR		L	S	RR																								
Contact with poorly maintained Front of House furnishings and fittings, such as loose handrails or stair nosings, loose carpets, or sharp/rough edges from damaged fixtures or fittings.	Members of the public may slip or trip over trip hazards or slip losing their footing due to loose handrails or stair nosings, causing serious injuries, fractures or sprains.	 Regular walk around of all public areas checking lighting and removing any potential trip hazards Weekly check of handrails stair nosings and carpets on all staircases and in the auditorium Staff encouraged to feed back and report any identified issues or damage Show report to detail any issues raised such as any slips or trips and near misses or customers complaining of damaged seating Maintenance log books kept to record 	2	4	8																												

Page 1 reference BUXOPFOH0031

		action taken if planned					
Damaged or broken seats	Members of the public may suffer injury due to falling off broken seats or trapping fingers in damaged parts.	 Seats visually checked pre show to identify any broken or damaged seating. Maintenance team repair damaged seating as soon as it is reported or seats put out of commission if immediate repair is not possible Contractors appointed to repair any issues that cannot be repaired in house. 	2	3	6		
Spillages	Potential for musculoskeletal or impact injury due to slips caused by contact with spilled liquids.	Spills are cleared up as soon as they are identified and in public areas are coned off and monitored unto they can be safely cleared away	2	3	6		
Unauthorised access to restricted areas	Potential for injury to unauthorised persons accessing restricted areas, or for harm or damage to persons or property within the theatre.	Access to restricted areas from publicly accessible front of house areas are locked and clearly signed no admittance	1	4	4		

Page 1 reference BUXOPFOH0031